

APPENDIX – XII

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

NO. J.S.V A.E Chamba 110

Dated: 28/5/23

It is certified that an inspection team headed by Sh. Manoj Kumar, Assistant Engineer, From Irrigation & Public Health Department (Jal Shakti Vibhag) Himachal Pradesh inspected the DAV Public School Mohalla Hardaspura, Distt. Chamba (HP) 176318 on dated 01-05-2023 and found that the DAV Public School Mohalla Hardaspura Distt. Chamba (HP) has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central / State / .T. Govt.


The above is valid for a period of Two Years.

Signature with Seal:

Name

Designation

Name & Address of the Office/Department


Assistant Engineer
Jal Shakti Sub-Division
Chamba (HP)

To
Principal
DAV Public School
Mohalla Hardaspura, PO Hardaspura
Tehsil and Distt. Chamba (HP) 176318


PRINCIPAL
DAV PUBLIC SCHOOL
CHAMBA 176318


VICE-CHAIRMAN
DAV PUBLIC SCHOOL
CHAMBA 176318